

2013 Straphangers Campaign State of the Platforms Census

Conditions Observed at 862 Platforms*

MEASUREMENT	PERCENTAGE
No garbage can observed on platform	3% (30/862)
Overflowing garbage can observed	2% (17/832)
Garbage bags on platform	4% (35/862)
Staircases/handrails in disrepair	13% (115/862)
Exposed wiring	24% (205/862)
Substantial areas of missing tile	26% (226/862)
Substantial graffiti	32% (279/862)
Substantial floor cracks	39% (335/862)

* Based on a Straphangers Campaign census of all accessible 862 platforms in the MTA New York City Transit subway system, June to August 2013.

